

Tês de redução a 90°


Reducing tees 90°

Tês de réduction à 90°

Tes 90° reducidas



*20 41 2004 000



d	d1	A	B	C	D	E	F	G	H	Gr	Quant	Nº Código
20	16	135	82	46	39	39	35	17	17	110	•16x10	20 41 2004 103
25	20	149	98	52	41	46	39	22	22	163	•12x10	20 41 2004 105
32	25	178	104	64	52	52	41	27	26	230	•80	20 41 2004 110
40	32	208	136	78	61	64	52	34	33	419	•40	20 41 2004 115
50	40	239	150	92	68	78	61	41	41	623	•25	20 41 2004 120
63	50	296	182	109	83	92	68	51	52	1030	•16	20 41 2004 125
75	63	318	208	132	107	109	83	64	65	1500	•8	20 41 2004 130
90	75	402	246	151	131	132	107	76	78	2400	•5	20 41 2004 135
110	90	562	302	175	166	151	131	94	92	4560	•2	20 41 2004 140

d	d1	I	J	K	L	M	N	O	P
20	16	12	12	3	22	22	12	7	3.5
25	20	12	7	3.5	26	27	13	10	4
32	25	13	10	4	33	34	19	12	5
40	32	19	12	5	41	41	23	13	6
50	40	23	13	6	52	51	31	13	6.5
63	50	31	13	6.5	65	64	39	22	7
75	63	39	22	7	77	76	40	23	8
90	75	40	23	8	92	94	57	31	8
110	90	57	31	8	114	112	57	36	9