

Tês com saída roscada macho


Male union tees 90°

Tês à 90° mâle

Tes 90° macho



*20 41 2086 000



d	d ₁	A	B	C	D	E	F	G	H	Gr	Quant	Nº Código
16	" 1/2	101	55	39	17	17	12	12	3	63	• 16x20	20 41 2086 003
16	" 3/4	101	58	39	17	17	12	12	3	63	• 16x20	20 41 2086 004
20	" 1/2	117	64	46	22	22	12	7	3.5	104	• 12x15	20 41 2086 005
20	" 3/4	117	66	46	22	22	12	7	3.5	104	• 12x15	20 41 2086 006
20	1"	117	68	46	22	22	12	7	3.5	113	• 13x15	20 41 2086 007
25	" 1/2	130	72	52	27	26	13	10	4	129	• 10x15	20 41 2086 009
25	" 3/4	130	72	52	27	26	13	10	4	132	• 10x15	20 41 2086 010
25	1"	130	74	52	27	26	13	10	4	133	• 16x10	20 41 2086 011
32	" 1/2	152	78	64	34	33	19	12	5	196	• 100	20 41 2086 013
32	" 3/4	152	79	64	34	33	19	12	5	206	• 100	20 41 2086 014
32	1"	152	83	64	34	33	19	12	5	204	• 85	20 41 2086 015
40	1"	178	96	78	41	42	23	13	6	367	• 50	20 41 2086 019
40	1" 1/4	178	101	78	41	42	23	13	6	368	• 50	20 41 2086 020
40	1" 1/2	178	111	78	41	42	23	13	6	373	• 50	20 41 2086 021

Tês com saída roscada macho


Male union tees 90°

Tês à 90° mâle

Tes 90° macho



*20 41 2086 000



d	d ₁	A	B	C	D	E	F	G	H	Gr	Quant	Nº Código
50	1" 1/2	199	115	92	51	52	31	13	6.5	528	•30	20 41 2086 025
50	2"	199	115	92	51	52	31	13	6.5	538	•30	20 41 2086 026
63	2"	248	138	109	64	65	39	22	7	717	•20	20 41 2086 030
75	2"	276	171	132	76	78	40	23	8	1348	•10	20 41 2086 059
75	2" 1/2	276	171	132	76	78	40	23	8	1280	•10	20 41 2086 060
75	3"	276	171	132	76	78	40	23	8	1416	•10	20 41 2086 061
90	3"	344	196	151	94	92	57	31	8	2250	•6	20 41 2086 065
110	4"	480	220	175	112	113	57	36	9	3680	•4	20 41 2086 070