

Válvulas de encaixe rápido transição M/F- porca única


Single union transition quick coupling ball valves M/F

Vannes de transition M/F p/ tuyaux en PE - simple union

Válvulas de transición M/H para PE - una tuerca



02 71 2079 000



d	G	DN	A	B	C	H	L	M	S	Z	L1	L2	Gr	Quant	Nº Código
16	" 1/2	15	47	45	40	69	103	35	10	47	41	15	75	B 35	02 71 2079 003
20	" 1/2	15	47	45	40	69	103	35	10	47	41	15	73	B 35	02 71 2079 005
20	" 3/4	15	47	45	40	69	103	35	10	47	41	16	73	B 35	02 71 2079 006
25	" 3/4	20	67	70	46	103	135	53	17	70	49	16	191	C 40	02 71 2079 010
32	1 "	25	67	70	58	103	147	53	17	68	60	19	220	C 40	02 71 2079 015
40	1" 1/4	32	93	92	69	139	185	64	21	91	73	21	456	C 15	02 71 2079 021
50	1" 1/2	40	93	92	84	139	203	64	21	93,5	87,5	22	542	C 15	02 71 2079 026
63	2 "	50	113	105	111	162	236	73	23	105	105	26	950	C 7	02 71 2079 030